

Aquece Rio Test Event 2015 - 7-23 August 2015

Equipment Replacement/Repair Requests - Granted in accordance with Equipment Regulation 3

No.	Date	Class	Country	Sail Number	Item of Equipment	Reason for Replacement/Repair
1	14-Aug	49er	FRA	9	Port Wing	Repair of collision damage
2	14-Aug	RS:X (M)	MEX	1	Board	Repair
3	14-Aug	RS:X (M)	GBR	1	Board	Small repair to bow
4	14-Aug	RS:X (M)	RUS	1	Board	Repair
5	15-Aug	RS:X (M)	BRA	1	Board	Repair
6	15-Aug	RS:X(M)	EGY	9	Board & Fin	Repair
7	15-Aug	49er	AUS	3	Centreboard & Spinnaker	Repair
8	15-Aug	Nacra17	DEN	248	Boat bow	Repair of collision damage
9	15-Aug	Nacra17	ARG	226	Boat port hull	Repair of collision damage
10	16-Aug	Laser Radial	USA	19711	Top section replacement	Broken top section
11	16-Aug	49erFX	SIN	33	Bolt rope and luff tape on mainsail	Repair
12	16-Aug	Laser	CZE	207193	Daggerboard	Blistering board, replacement
13	16-Aug	RS:X (M)	JPN	11	Mainsail batten cap	Broken, replacement
14	17-Aug	Laser Radial	LTU	202750	Bottom mast	Bottom mast bent, replacement
15	17-Aug	Nacra17	AUS	2	Mainsheet system	Mainsheet blocks broken, replacement
16	17-Aug	Nacra17	GBR	201	Hull bow	Repair of damage
17	17-Aug	RS:X (M)	BRA	1	Batten widge	Broken, replacement
18	17-Aug	RS:X (M)	BRA	1	Fin	Small crack, denied replacement
19	18-Aug	RS:X (M)	RUS	271	Batten widge	Broken, replacement
20	18-Aug	RS:X (W)	FRA	4	Batten 6	Broken, replacement
21	18-Aug	RS:X (M)	MEX	1	Mast track	Broken, replacement
22	18-Aug	RS:X (M)	EGY	9	Board	Repair to bow
23	18-Aug	Finn	AUS	41	Centreboard and hull bow	Repair to damage
24	18-Aug	49erFX	ESP	23	Mast track	Repair to broken track
25	18-Aug	49erFX	GER	161	Daggerboard	Damaged, replacement
26	18-Aug	Laser	AUS	199012	Daggerboard	Damaged, repair
27	19-Aug	Nacra17	ITA	200	Hull bow	Repair of collision damage
28	19-Aug	Nacra17	ITA	200	Hull near daggerboard case	Repair
29	19-Aug	Nacra17	ARU	212	Hull daggerboard packing	Repair
30	19-Aug	Nacra17	ARG	226	Hull side	Repair of collision damage
31	19-Aug	Nacra17	URU	147	Hull daggerboard packing	Repair
32	19-Aug	49erFX	GBR	22	Rudder blade	Repair
33	20-Aug	Nacra17	BRA	237	Tiller bar	Broken, replacement
34	20-Aug	Nacra17	AUS	2	Mainsheet system	Broken, replacement
35	21-Aug	Laser Radial	GBR	202411	Tiller extension	Broken, replacement
36	21-Aug	Nacra17	AUS	2	Starboard centreboard	Repair
37	21-Aug	Nacra17	NZL	222	Stern of starboard hull	Repair
38	21-Aug	Nacra17	USA	278	Tiller bar	Broken, replacement
39	21-Aug	49er	ESP	900	Rudder blade and daggerboard	Repair
40	21-Aug	49erFX	GBR	22	Control line	Chafe, replacement
41	21-Aug	470 (W)	CHN	619	Rudder blade	Broken, replacement