

Post Inspection Equipment Replacement/Repair Requests - Granted in accordance with Equipment Regulation 3

No.	Date	Class	Country	Item of Equipment	Repair or Replacement	Reason
1	06-Aug	Finn	FIN	Rudder	Repair	Damage to trailing edge
2	06-Aug	Laser	BEL	Daggerboard	Repair	Damage
3	06-Aug	Laser	POL	Daggerboard	Repair	Damage
4	06-Aug	Laser	BRA	Centreboard	Repair	Damage to centreboard stopper
5	06-Aug	Laser	GBR	Centreboard	Repair	Scratches along length of the board.
6	06-Aug	Finn	GBR	Centreboard Case	Repair	Damage to trailing edge of centreboard case
7	06-Aug	49er	SUI	Daggerboard	Repair	Damage to handle holes
8	06-Aug	Finn	BRA	Centreboard Case	Repair	Damage to leading and trailing edges of centreboard case
9	07-Aug	RS:X M	GER	Centreboard	Replacement	Centreboard is bent
10	07-Aug	Finn	FIN	Rudder	Repair	Damage to leading edge
11	07-Aug	Laser Radial	SWE	Daggerboard	Repair	Damage
12	07-Aug	Laser	NOR	Self Bailer	Repair	Not working
13	07-Aug	Laser	NOR	Hull	Repair	Damage to gunwhale
14	07-Aug	RS:X W	DEN	Board	Repair	Small chips to rails and bottom of board
15	07-Aug	Laser Radial	NED	Daggerboard	Repair	Damage to leading edge of the daggerboard
16	07-Aug	RS:X M	POL	Fin	Repair	Add NP washers to fin bolts
17	07-Aug	RS:X W	ESP	Fin	Repair	Sanding gelcoat repair
18	07-Aug	Laser	SWE	Self Bailer	Repair	Not working
19	07-Aug	Laser	MEX	Top Mast	Replacement	Bent
20	07-Aug	Laser	GUA	Daggerboard	Repair	Damage to trailing edge tip
21	08-Aug	Finn	GBR	Sail	Repair	Sail branding application
22	08-Aug	Finn	EST	Correctors	Repair	Attach Correctors
23	08-Aug	Finn	NED	Rudder	Repair	Damage to leading edge
24	08-Aug	Laser	SWE	Daggerboard	Repair	Damage to trailing edge tip
25	08-Aug	RS:X W	FIN	Fin	Repair	Damage to trailing edge
26	08-Aug	RS:X W	POL	Board	Repair	Damage to starboard side of board
27	08-Aug	RS:X M	POL	Board and Fin	Repair	Damage to tip of board and tip of fin
28	08-Aug	Laser Radial	SWE	Top Mast	Replacement	Bent
29	08-Aug	Laser	NOR	Hull	Repair	Damage to bow
30	08-Aug	Finn	NZL	Sail	Repair	Sail branding application
31	09-Aug	RS:X W	ESP	Fin	Repair	Damage to leading edge
32	09-Aug	Nacra 17	GER	Daggerboard	Repair	Damage to trailing edge tip of both boards
33	09-Aug	Laser	ESP	Hull	Repair	Damage to bow
34	09-Aug	RS:X W	GBR	Fin	Repair	Damage
35	09-Aug	RS:X M	HKG	Mast Track	Replacement	Broken
36	09-Aug	RS:X M	GBR	Batten Cam	Replacement	Broken
37	09-Aug	Nacra 17	GRE	Jib	Repair	Stitching on zip luff
38	09-Aug	Laser	KOR	Hull	Repair	Damage
39	10-Aug	Laser	NOR	Dagger friction pad	Repair	Not working
40	10-Aug	Laser	BRA	Daggerboard	Repair	Damage to trailing edge
41	10-Aug	Nacra 17	ESP	Daggerboard Cases	Repair	Damage to trailing edge of both daggerboard cases
42	10-Aug	Finn	EST	Rudder	Repair	Damage to trailing edge
43	10-Aug	Laser	DEN	Hull	Repair	Damage to bow
44	10-Aug	Nacra 17	BRA	Daggerboards	Repair	Sanding along length of boards
45	10-Aug	Nacra 17	ITA	Daggerboard Case	Repair	Damage to board case
46	10-Aug	Finn	USA	Boom	Repair	Replace fitting
47	10-Aug	49erFX	BRA	Hull	Repair	Wash and polish hull
48	10-Aug	RS:X W	GBR	Fin	Repair	Damage to trailing edge
49	10-Aug	49erFX	ESP	Daggerboard	Repair	Damage to bottom of board
50	10-Aug	Nacra 17	GRE	Boom	Replacement	Bent
51	10-Aug	Laser	GER	Centreboard	Replacement	Equipment limitation sticker damaged/missing
52	11-Aug	RS:X M	CRO	Board	Replacement	Damaged in collision
53	11-Aug	Finn	DEN	Sail	Repair	Damage to clew
54	11-Aug	Nacra 17	AUS	Sail	Replacement	Replacement National flag branding
55	11-Aug	RS:X M	HUN	Board	Replacement	Damage to board and mast track not working
56	11-Aug	Finn	GBR	Rudder	Repair	Damage
57	11-Aug	Laser	USA	Top Mast	Replacement	Bent
58	11-Aug	Nacra 17	DEN	Daggerboard and Hull	Repair	Damage to trailing edge of board and board case
59	11-Aug	RS:X M	POL	Boom	Replacement	Replacement equipment limitation sticker
60	11-Aug	RS:X M	HKG	Sail	Replacement	Replacement equipment limitation sticker
61	11-Aug	RS:X W	POL	Boom	Replacement	Replacement equipment limitation sticker
62	11-Aug	470 M	GBR	Spinnaker Pole	Repair	Pole end fitting loose
63	11-Aug	49er	POL	Gennaker Pole blocks	Replacement	Block not working
64	11-Aug	49er	CHI	Jib	Replacement	
65	11-Aug	49er	CRO	Jib	Repair	Broken jib batten
66	11-Aug	470 M	AUS	Spinnaker Pole	Replacement	Lost in capsizes (subsequently found and reused)
67	11-Aug	470 W	CHI	Spinnaker Pole	Repair	Damage
68	11-Aug	RS:X W	POL	Fin	Replacement	Own fin broken, replacement supplied by NP
69	11-Aug	470 W	GER	Jib	Replacement	Damaged
70	12-Aug	Nacra 17	AUS	Sail	Repair	Replacement National flag branding and repair to batten pocket
71	12-Aug	Laser Radial	NED	Top Mast	Replacement	Bent
72	12-Aug	470 M	GER	Spinnaker	Replacement	Torn
73	12-Aug	470 M	GER	Spinnaker Pole	Replacement	Lost in capsizes
74	12-Aug	470 M	GER	Rudder Blade	Replacement	Damaged
75	12-Aug	470 W	BRA	Centreboard	Repair	Damaged
76	12-Aug	Nacra 17	ARG	Sail	Repair	Damage to batten pocket
77	12-Aug	Nacra 17	AUS	Daggerboards	Repair	Damage
78	12-Aug	Nacra 17	ARU	Rudder Fittings	Repair	Tighten and refit rudder hangings

Post Inspection Equipment Replacement/Repair Requests - Granted in accordance with Equipment Regulation 3

No.	Date	Class	Country	Item of Equipment	Repair or Replacement	Reason
79	12-Aug	RS:X W	ITA	Boom	Replacement	Replacement equipment limitation sticker
80	12-Aug	Nacra 17	GBR	Daggerboards	Repair	Damage to tip of board
81	12-Aug	Laser Radial	BLR	Top Mast	Replacement	Bent
82	12-Aug	Laser	USA	Daggerboard	Repair	Replacement daggerboard stopper
83	13-Aug	Nacra 17	ARU	Mast Step & Boom	Replacement	Damage
84	13-Aug	Nacra 17	ARU	Mainsail	Repair	Damage to batten pocket
85	13-Aug	Finn	ITA	Hull	Repair	Hole in starboard side
86	13-Aug	Laser Radial	BRA	Self Bailer	Repair	Not working
87	13-Aug	470 M	POL	Boom	Repair	Boom end fitting
88	13-Aug	470 W	BRA	Mast	Replacement	Bent
89	13-Aug	470 M	GER	Mast	Replacement	Bent mast & detached spreaders
90	13-Aug	Finn	GRE	Boom	Replacement	Bent
91	13-Aug	Finn	FIN	Rudder	Replacement	Broken
92	13-Aug	Nacra 17	ESP	Rudder Fittings	Repair	Damage
93	13-Aug	Nacra 17	ESP	Daggerboard	Repair	Damage to tip
94	13-Aug	470 M	SWE	Hull	Repair	Hole in port side and damage to hull structure
95	13-Aug	Nacra 17	BRA	Daggerboards	Repair	Sanding of both daggerboards
96	13-Aug	Nacra 17	AUT	Daggerboard	Repair	Damaged
97	13-Aug	Laser Radial	TUR	Top Mast	Repair	Bent
98	13-Aug	Laser Radial	GBR	Boom	Replacement	Boom end fitting/mainsheet attachment
99	13-Aug	49er	SWE	Daggerboard	Repair	Damage to trailing edge
100	13-Aug	Finn	NED	Mast	Repair	Damage
101	13-Aug	Nacra 17	GBR	Daggerboard	Repair	Damage to leading edge
102	13-Aug	RS:X W	RUS	Boom	Replacement	Replacement equipment limitation sticker
103	13-Aug	Laser Radial	BEL	Daggerboard	Repair	Damage to tip
104	13-Aug	Nacra 17	ARU	Mainsheet System	Replacement	Replace whole mainsheet system due to damage
105	14-Aug	Nacra 17	ITA	Daggerboard	Replacement	Broken board in half
106	14-Aug	Nacra 17	NZL	Jib	Repair	Luff end of batten pocket
107	14-Aug	RS:X W	CHN	Batten	Replacement	Batten degrading
108	14-Aug	Laser Radial	DEN	Self Bailer	Repair	Not working
109	14-Aug	470 W	FRA	Centreboard	Repair	Damage to trailing edge
110	14-Aug	470 M	BRA	Hull	Repair	Damage to port side of hull
111	14-Aug	470 W	SIN	Hull	Repair	Damage to port side of hull
112	14-Aug	470 W	RUS	Hull	Repair	Damage to port side of hull
113	14-Aug	Finn	NED	Rudder	Repair	Damage
114	14-Aug	Nacra 17	AUS	Spinnaker Sheets	Replacement	Frayed sheets requiring replacement
115	14-Aug	Nacra 17	ARG	Daggerboard case	Repair	Damage
116	14-Aug	Nacra 17	FRA	Spreaders	Replacement	Broken
117	14-Aug	49er	POL	Tiller	Replacement	Damage
118	14-Aug	49erFX	ESP	Daggerboard	Repair	Damage to trailing edge
119	14-Aug	49er	POL	Rudderblade	Replacement	Damaged in collision
120	14-Aug	49er	AUS	Spreaders	Repair	Refix spreaders in position - loose
121	15-Aug	49erFX	DEN	Footstraps	Replacement	Original footstraps causing discomfort
122	15-Aug	470 W	AUS	Rudder Blade	Repair	Damage to leading edge
123	15-Aug	49erFX	IRL	Spinnaker	Repair	Two small tears near luff at head
124	15-Aug	Nacra 17	NZL	Daggerboards	Repair	Sanding scratches along length of board
125	15-Aug	Nacra 17	AUT	Daggerboards	Repair	Sanding scratches along length of board
126	15-Aug	Laser Radial	NED	Top Mast	Replacement	Bent
127	15-Aug	49erFX	ARG	Jib	Replacement	Damaged beyond repair
128	15-Aug	49er	GBR	Jib	Replacement	Lost at sea
129	15-Aug	49er	SUI	Tiller & Rudder stock	Replacement	Damaged
130	15-Aug	Nacra 17	ARG	Daggerboard case	Repair	Damage
131	15-Aug	Nacra 17	BRA	Daggerboard	Repair	Sanding scratches along length of board
132	15-Aug	49erFX	CAN	Wing	Repair	Damage
133	15-Aug	49erFX	CHI	Jib	Replacement	Damaged beyond repair
134	15-Aug	49er	BEL	Jib	Replacement	Damaged beyond repair
135	15-Aug	49er	ESP	Jib	Replacement	Lost at sea
136	15-Aug	49er	JPN	Jib and Mainsail Battens	Replacement	Jib lost at sea and replacement mainsail battens
137	15-Aug	49er	SUI	Jib	Replacement	Damaged beyond repair
138	15-Aug	49er	IRL	Jib and spinnaker sock fitting	Repair	Replacement jib and repair to spinnaker sock
139	15-Aug	49er	POL	Jib	Replacement	Damaged beyond repair
140	15-Aug	49er	BRA	Jib	Replacement	Broken battens
141	15-Aug	49er	POR	Jib	Replacement	Damaged beyond repair
142	15-Aug	49er	CHI	Jib	Replacement	Jib luff zip damaged
143	15-Aug	49er	ARG	Jib	Replacement	Damaged beyond repair
144	15-Aug	49er	NZL	Jib	Replacement	Damaged beyond repair
145	15-Aug	470 M	POL	Mast	Replacement	Bent
146	15-Aug	470 W	AUS	Jib	Replacement	Damaged beyond repair
147	15-Aug	470 M	SLO	Jib Battens	Repair	Damage to batten pocket
148	15-Aug	470 M	TUR	Jib	Replacement	Damaged beyond repair
149	15-Aug	470 M	CHI	Spinnaker pole	Replacement	Lost at sea
150	15-Aug	470 W	AUS	Boom	Replacement	Boom end fitting broken, unrepairable
151	15-Aug	470 M	POL	Spinnaker Pole	Replacement	Lost at sea
152	15-Aug	470 M	USA	Mast	Replacement	Bent
153	15-Aug	470 M	FRA	Mast	Replacement	Damaged
154	15-Aug	470 W	CHI	Jib	Replacement	Damaged beyond repair
155	15-Aug	470 M	ESP	Jib	Replacement	Damaged beyond repair
156	15-Aug	470 M	GBR	Jib	Replacement	Damaged beyond repair
157	15-Aug	470 W	GBR	Jib	Replacement	Damaged beyond repair
158	15-Aug	470 W	BRA	Jib	Replacement	Damaged beyond repair
159	15-Aug	470 W	USA	Jib	Replacement	Damaged beyond repair
160	15-Aug	470 W	ESP	Jib	Replacement	Damaged beyond repair
161	15-Aug	470 M	SWE	Jib	Replacement	Damaged beyond repair
162	15-Aug	470 W	SUI	Jib	Replacement	Damaged beyond repair
163	15-Aug	470 W	GER	Mainsail	Replacement	Damaged beyond repair
164	15-Aug	470 W	POL	Jib	Replacement	Damaged beyond repair

Post Inspection Equipment Replacement/Repair Requests - Granted in accordance with Equipment Regulation 3

No.	Date	Class	Country	Item of Equipment	Repair or Replacement	Reason
165	15-Aug	470 W	SIN	Jib	Replacement	Damaged beyond repair
166	15-Aug	470 W	NZL	Jib	Replacement	Damaged beyond repair
167	15-Aug	470 W	AUT	Jib	Replacement	Damaged beyond repair
168	15-Aug	470 M	AUT	Jib	Replacement	Damaged beyond repair
169	15-Aug	470 W	NED	Jib	Replacement	Damaged beyond repair
170	15-Aug	470 W	ISR	Jib	Replacement	Damaged beyond repair
171	15-Aug	470 M	CRO	Mast	Replacement	Bent
172	15-Aug	470 M	USA	Jib	Replacement	Damaged beyond repair
173	15-Aug	470 W	CHI	Jib	Replacement	Damaged beyond repair
174	15-Aug	470 M	BRA	Jib	Replacement	Damaged beyond repair
175	15-Aug	470 M	ARG	Mainsail	Replacement	Lost at sea
176	15-Aug	470 M	NZL	Jib	Replacement	Damaged beyond repair
177	15-Aug	470 M	ARG	Jib	Replacement	Damaged beyond repair
178	15-Aug	470 W	USA	Spinnaker pole	Repair	Pole topping lift eye replacement
179	15-Aug	470 M	CHI	Mast	Replacement	Bent
180	16-Aug	Laser	BRA	Daggerboard	Repair	Damage to trailing edge and bottom of board
181	16-Aug	470 W	GER	Jib	Replacement	Damaged beyond repair
182	16-Aug	470 W	FRA	Jib	Replacement	Damaged beyond repair
183	16-Aug	470 M	FRA	Jib	Replacement	Damaged beyond repair
184	16-Aug	470 M	GER	Jib	Replacement	Damaged beyond repair
185	16-Aug	470 M	ISR	Jib	Replacement	Damaged beyond repair
186	16-Aug	470 M	ANG	Jib	Replacement	Damaged beyond repair
187	16-Aug	470 M	CAN	Jib	Replacement	Damaged beyond repair
188	16-Aug	470 M	FIN	Jib	Replacement	Damaged beyond repair
189	16-Aug	470 M	GRE	Jib	Replacement	Damaged beyond repair
190	16-Aug	470 W	POL	Spinnaker	Repair	Torn
191	16-Aug	470 M	ARG	Spinnaker	Replacement	Lost
192	16-Aug	470 W	GBR	Spinnaker Pole	Replacement	Lost
193	16-Aug	470 M	AUS	Mainsail	Repair	Damaged leech to be repaired as soon as possible. Spare sail to be used on 16/08/2016 until repair made
194	16-Aug	470 W	BRA	Centreboard	Repair	Damage to trailing edge
195	16-Aug	470 M	JPN	Jib	Replacement	Damaged beyond repair
196	16-Aug	470 W	JPN	Jib	Replacement	Damaged beyond repair
197	16-Aug	470 M	KOR	Jib	Replacement	Damaged beyond repair
198	16-Aug	470 M	RSA	Jib	Replacement	Damaged beyond repair
199	16-Aug	470 M	CRO	Jib	Replacement	Damaged beyond repair
200	16-Aug	470 M	FRA	Mainsail	Repair	Damage to batten pocket
201	16-Aug	49er	FRA	Jib	Repair	Broken middle batten
202	16-Aug	49er	ESP	Forestay	Replacement	Broken